

## *NorBay Consulting*

---

*LOGICAL*

*ENVIRONMENTAL*

*SOLUTIONS*

---

*(415) 507-9786 Phone  
(415) 507-9760 Fax*

*2563 Heatherstone Drive  
San Rafael, California 94903*

March 30, 2011

Mr. Joe Burns  
City of Sausalito  
420 Litho Street  
Sausalito, CA 94965

**SUBJECT: LEAD IN PAINT INSPECTION  
MLK BUILDING 5 FASCIA & WINDOWS  
SAUSALITO, CALIFORNIA**

Dear Mr. Burns:

NorBay Consulting is pleased to provide the results from the lead in paint inspection conducted on the exterior fascia and windows on the south side of Building 5 on the MLK property. Said inspection was conducted on March 29, 2011 by Bob Gerhold, CDPH Lead Inspector/Assessor #I2108.

A total of ten (10) readings for lead in paint were collected utilizing a RMD direct reading instrument. No bulk paint chip samples were collected.

### **RESULTS**

- Lead based paint was located on the exterior fascia.
- Lead based paint was not located on the exterior window system.

### **RECOMMENDATIONS**

Current EPA and HUD guidelines recommend that surfaces containing lead based paint in damaged condition to be considered "lead-based paint hazards" and should be addressed through abatement (permanent removal) or interim controls (temporary). Surfaces containing lead based paints in intact condition should be monitored, but are not considered to be "lead based paint hazards".

At the time of our inspection the paint on the exterior fascia of Building 5 was damaged thus is considered a "lead based paint hazard".

At present, there are no state or federal laws dealing with mandatory abatement following the identification of lead containing or lead based paints prior to disturbance. However, in 1993 the Occupational Safety and Health Administration promulgated legislation (29 CFR 1926.62 and 8 CCR 1532.1) entitled "Lead Exposure in the Construction Industry" which deals with worker exposure to lead.

Lead in Paint Inspection  
MLK – Building 5  
Sausalito, California

It should be noted that aside from the HUD definition of lead-based paint (1.0 mg/cm<sup>2</sup>), OSHA regulates worker protection and work practices on building components containing any detectable amounts of lead. Therefore, components determined to contain less than 1.0 mg/cm<sup>2</sup> may still be subject to OSHA regulations, if these materials are to be disturbed. This standard essentially states that work, involving components containing any amount of lead must follow certain guidelines. These guidelines include but are not limited to training, personal protective equipment and specific work practices whenever workers disturb lead in any concentration because the disturbance may result in airborne exposures over action or permissible exposure limits.

This legislation requires that any task that may potentially expose workers to any concentration of lead be monitored to determine workers eight-hour time weighted average (TWA) exposure to lead. Prior to conduction of activities that may generate a lead exposure, such workers must be properly fitted with respiratory protection and protective clothing until personal eight-hour TWA results reveal exposures within acceptable levels.

Any proposed renovation/demolition, which may involve the removal of building materials with lead based and/or lead containing painted surfaces, should include provisions to minimize the potential for airborne release of lead contaminated dust. It is recommended, as a minimum, that demolition of building materials which have lead-based and/or lead-containing paints be conducted with the materials kept in a wetted state and removed in sections, as feasible, to reduce the potential for airborne lead emissions.

NorBay Consulting appreciates the opportunity to provide you with these services. Attached you will find a spread sheet of lead readings collected during the inspection.

If you have any questions regarding this report or if you require additional information please do not hesitate to contact me at (415) 507-9786.

Respectfully,  
NORBAY CONSULTING

*Bob Gerhold*

Bob Gerhold  
Certified Asbestos Consultant # 92-0157  
CDPH Lead Inspector/Assessor # I2108

Lead in Paint Inspection  
MLK – Building 5  
Sausalito, California

**LEAD IN PAINT READINGS AS PER  
RMD DIRECT READING INSTRUMENT**

Readings in **green** indicate lead containing paint

Readings in **black** indicate lead based paint or glazing

## *NorBay Consulting*

---

*LOGICAL*

*ENVIRONMENTAL*

*SOLUTIONS*

---

*(415) 507-9786 Phone  
(415) 507-9760 Fax*

*2563 Heatherstone Drive  
San Rafael, California 94903*

March 3, 2011

Mr. Joe Burns  
City of Sausalito  
420 Litho Street  
Sausalito, CA 94965

**SUBJECT: ASBESTOS & LEAD IN PAINT  
PRE-RENOVATION INSPECTION  
MLK LOCATIONS, SAUSALITO, CA**

Dear Mr. Burns:

NorBay Consulting is pleased to provide the visual inspection and analytical results from the asbestos and lead in paint inspection conducted in the gymnasium and storage areas of the MLK property. Said inspection was conducted on February 28, 2011 by Bob Gerhold, Certified Asbestos Consultant #92-0159 and CDPH Lead Inspector/Assessor #I2108.

In addition to conducting visual inspections a total of two (2) samples of suspect asbestos containing building materials were collected and delivered under chain of custody protocol for analysis for asbestos content by Polarized Light Microscopy (PLM). Forensic Analytical Laboratories located in Hayward, California conducted the analysis.

A total of twelve (12) readings for lead in paint were collected utilizing a RMD direct reading instrument. No bulk paint chip samples were collected.

### **RESULTS**

#### Gymnasium

- Lead based paint is located on the exterior window systems;
- Detectable levels of lead are located on the interior window systems;
- No asbestos was detected in the exterior window caulking;
- No asbestos was detected in the interior acoustical ceiling tiles.

#### Storage Areas

- Asbestos containing pipe insulation was observed above the storage areas;
- No other suspect asbestos containing materials were observed in the storage areas available for inspection;
- Mechanical equipment, associated with the storage areas appears to have been removed.

Asbestos & Lead in Paint  
Two locations on the MLK Site  
Sausalito, California

## **RECOMMENDATIONS**

Current EPA and HUD guidelines recommend that surfaces containing lead based paint in damaged condition to be considered “lead-based paint hazards” and should be addressed through abatement (permanent removal) or interim controls (temporary). Surfaces containing lead based paints in intact condition should be monitored, but are not considered to be “lead based paint hazards”.

At the time of our inspection the paint on the exterior window systems of the gymnasium was damaged thus are considered “lead based paint hazards”.

At present, there are no state or federal laws dealing with mandatory abatement following the identification of lead containing or lead based paints prior to disturbance. However, in 1993 the Occupational Safety and Health Administration promulgated legislation (29 CFR 1926.62 and 8 CCR 1532.1) entitled "Lead Exposure in the Construction Industry" which deals with worker exposure to lead.

It should be noted that aside from the HUD definition of lead-based paint ( $1.0 \text{ mg/cm}^2$ ), OSHA regulates worker protection and work practices on building components containing any detectable amounts of lead. Therefore, components determined to contain less than  $1.0 \text{ mg/cm}^2$  may still be subject to OSHA regulations, if these materials are to be disturbed. This standard essentially states that work, involving components containing any amount of lead must follow certain guidelines. These guidelines include but are not limited to training, personal protective equipment and specific work practices whenever workers disturb lead in any concentration because the disturbance may result in airborne exposures over action or permissible exposure limits.

This legislation requires that any task that may potentially expose workers to any concentration of lead be monitored to determine workers eight-hour time weighted average (TWA) exposure to lead. Prior to conduction of activities that may generate a lead exposure, such workers must be properly fitted with respiratory protection and protective clothing until personal eight-hour TWA results reveal exposures within acceptable levels.

Any proposed renovation/demolition, which may involve the removal of building materials with lead based and/or lead containing painted surfaces, should include provisions to minimize the potential for airborne release of lead contaminated dust. It is recommended, as a minimum, that demolition of building materials which have lead-based and/or lead-containing paints be conducted with the materials kept in a wetted state and removed in sections, as feasible, to reduce the potential for airborne lead emissions.

The asbestos containing pipe insulation located above the storage area is also in damaged condition thus should be repaired or remediated. The repair or remediation of this material should be conducted by a licensed asbestos abatement contractor who is familiar with and will abide by the strict rules and regulations regarding the removal, packaging and disposal of asbestos containing materials.

Asbestos & Lead in Paint  
Two locations on the MLK Site  
Sausalito, California

NorBay Consulting appreciates the opportunity to provide you with these services. Attached you will find the laboratory reports and chain of custody forms for all samples collected. Also attached is a spread sheet of lead readings collected during the inspection.

If you have any questions regarding this report or if you require additional information please do not hesitate to contact me at (415) 507-9786.

Respectfully,  
NORBAY CONSULTING

*Bob Gerhold*

Bob Gerhold  
Certified Asbestos Consultant # 92-0157  
CDPH Lead Inspector/Assessor # I2108

Asbestos & Lead in Paint  
Two locations on the MLK Site  
Sausalito, California

**LABORATORY REPORTS AND CHAIN  
OF CUSTODY FORMS**

**ASBESTOS BULK SAMPLES ANALYZED BY  
POLARIZED LIGHT MICROSCOPY (PLM)**

Asbestos & Lead in Paint  
Two locations on the MLK Site  
Sausalito, California

## **LEAD IN PAINT READINGS AS PER RMD DIRECT READING INSTRUMENT**

Readings in **green** indicate lead containing paint

Readings in **black** indicate lead based paint or glazing



NorBay Consulting  
2563 Heatherstone Drive  
San Rafael, CA 94903  
(415) 507-9786 Phone  
(415) 507-9760 Fax

Job Site: City of Sausalito  
MLK Gymnasium  
Sausalito, California

Project Number: 3932  
Analysis Requested: PLM  
Turn Around Time: 24 hr

Client ID#      Date      Location      Description

Client ID#	Date	Location	Description
3932-PLM-1	2/28/11	Exterior windows	Window caulking
3932-PLM-2	↓	Interior	Acoustical ceiling tiles

Notes: email results to Rohold@comcast.net

Bob Gerhold      2/28/11  
Relinquished by      Date

Bethy C      10 AM 3/1/11  
Received by      Date

Relinquished by      Date

Received by      Date



# Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

NorBay Consulting  
Robert Gerhold  
2563 Heatherstone Dr.  
  
San Rafael, CA 94903

**Client ID:** 3982  
**Report Number:** B145910  
**Date Received:** 03/01/11  
**Date Analyzed:** 03/02/11  
**Date Printed:** 03/02/11  
**First Reported:** 03/02/11

**Job ID/Site:** 3932 - City of Sausalito, MLK Gymnasium, Sausalito, CA

**FALI Job ID:** 3982

**Date(s) Collected:** 02/28/2011

**Total Samples Submitted:** 2

**Total Samples Analyzed:** 2

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
<b>3932-PLM-1</b>	11085257						
Layer: White Non-Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
<b>3932-PLM-2</b>	11085258						
Layer: Grey Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (35 %)      Fibrous Glass (45 %)							

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical Laboratories Inc. (FALI) at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by FALI to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by FALI. The client is solely responsible for the use and interpretation of test results and reports requested from FALI. Forensic Analytical Laboratories Inc. is not able to assess the degree of hazard resulting from materials analyzed. FALI reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.



