

DEPARTMENT OF PUBLIC WORKS  
 TREE MAINTENANCE ACTIVITIES PERFORMED AND PENDING  
 MARCH 2012

Page 1 of 3

<u>ADDRESS</u>	<u>TYPE OF TREE</u>	<u>DIAMETER</u>	<u>ALTERED (TRIM)</u>	<u>REMOVED</u>	<u>COMMENTS</u>
5 Miller Ave	Monterey Pine	54.4-in DBH (171-in CBH estimated)		Top removed, remainder pending PG&E strain guy relocation	Private - still requires PG&E coordination - no permit required (undesirable tree).
ROW at 81 Cazneau Ave	Coast Live Oak	37.7-in CBH	Pending		Application TRP11-252 received with arborist's report. Posted pending renewal or alteration. Approval pending.
ROW at 254 Glen Drive	Pittosporum Quercus	37.7-in CBH	Decision: View Claims Valid 31JAN12 Decision appealed 9FEB12 23FEB12		TRP 11-174 (Pittosporum) & TRP 11-394 (Quercus) received. Appeal of view claim 2/23 & 2/27 letter from Attorney responded to by DPW Director on 3/7. Trimming postponed until April 9.
ROW - Intersection between Sausalito Blvd & Spencer Ave on 40 Cooper Lane	Black Acacia	72" DBH 78" DBH			Co dominant trunks lean away from each other. 1 trunk leans over Spencer Ave; the other is a threat to property at Cooper Lane. Bartlett Tree exposed root collar, ivy & soil removed from

Tree Maintenance Activities March 15, 2012

ITEM NO. Comm 1 PAGE 1

DEPARTMENT OF PUBLIC WORKS  
 TREE MAINTENANCE ACTIVITIES PERFORMED AND PENDING  
 MARCH 2012

Page 2 of 3

<u>ADDRESS</u>	<u>TYPE OF TREE</u>	<u>DIAMETER</u>	<u>ALTERED (TRIM)</u>	<u>REMOVED</u>	<u>COMMENTS</u>
ROW at 506 Olive Street	DEDICATED Monterey Pine (see Memorandum with 2FEB12 packet)			Pending	bottom of tree to determine risk of failure. Two arborist reports, 1 from homeowner. Not a hazard. DPW Division Mgr contacted owner for update. Arborist Report from Bartlett Tree. Dedicated tree dying from bark beetles. Possibility of root damage and/or soil compaction resulted from construction adjacent. Women's Club notified. Posted 1/24/12. Removal pending.
309-311 "A" Third Street (Southview Park)	Arbutus			Completed 2-29-12	Removed due to damaging retaining wall for basketball court. Posted 1/24/12. Removed 2/29/12.

*Handwritten signature*


DEPARTMENT OF PUBLIC WORKS  
 TREE MAINTENANCE ACTIVITIES PERFORMED AND PENDING  
 MARCH 2012

Page 3 of 3

<u>ADDRESS</u>	<u>TYPE OF TREE</u>	<u>DIAMETER</u>	<u>ALTERED (TRIM)</u>	<u>REMOVED</u>	<u>COMMENTS</u>
99 Glen Drive	2) Coast Live Oak	23" DBH 18" DBH		Emergency Removal approved. Completed 2-15-12	TRP12-034 Emergency Tree Removal on private property granted by DPW Director 2/8 due to tree that fell on roof of house. Trees have advanced signs of sudden oak death root rot & are hazardous to two homes. Removed. Arborist report.
ROW at 112 Cazneau Ave	1) American Elm	12" DBH		Pending	Canopy hanging horizontally over house & root system has been damaged. PG&E topped the tree. Elite Tree to do the work. Arborist report.
ROW at 49 Cable Roadway	1) Oak			Completed 2-22-12	Emergency removal. Truck damaged two crotches on tree. City crews removed. No arborist report.

*Handwritten signature*

ITEM NO. Comm. 1 PAGE 3



Marin County Arborists Inc  
PO Box 2538, San Rafael CA 94912  
Tel: 415-457-8733 Fax: 415-455-8110

November 3, 2011

Wren Herring  
112 Cazneau Avenue  
Sausalito, CA 94965

Site: 112 Cazneau Avenue, Sausalito, CA 94965

Tree: T1 – Coast Live Oak tree (*Quercus agrifolia*) – 22" dbh – Located on 112 Cazneau  
T2 – American Elm tree (*Ulmus americana*) – 12" dbh – Located on City property

#### Arborist Report

T1 – This tree has beginning signs of Sudden Oak Death fungus as is evident by the red/black bleeding on trunk. This tree trunk is growing horizontally and its root system has damaged the adjacent gutter and stucco on the neighbors house. The entire canopy of this tree is growing over the house at 112 Cazneau. The hazard rating for this tree is 10 points out of a possible 12 points.

The damaged gutter will cause soil saturation at the base of this tree with heavy rain. Due to the presence of Sudden Oak Death fungus the increasing the risk of failure and potentially damaging the house or both houses, I recommend removing this tree. Removal of this tree won't impact soil stability. I recommend retaining the roots and allow it to resprout and repairing the gutter.

ISA guidelines doesn't provide an appraised value for hazardous trees. Replacement planting with 15 gallon Coast Live Oak on upper slope.

Neighboring Oak is also infected with Sudden Oak Death. This tree is being preserved and monitored for changes in health.

T2 – This tree is located on the City of Sausalito property. It is under high voltage wires and has been topped by PG&E.

The horizontal growth that has not been pruned is becoming very heavy and growing into and over the house at 112 Cazneau. This tree has poor structure due to prior topping. Any attempts to balance the trees canopy would require large heading (topping) cuts on the side branches. This is not a recommended procedure.

Removal of this tree is my recommendation. Adjacent trees and shrubs will fill the void caused by this removal. ISA appraised value for this tree is \$875.00. Removal of this tree won't impact erosion or stability

Report completed by:



Louie P. Brunn  
Marin County Arborists, Inc.  
Certified Arborist # 5695



