## LEGEND:



AREA OF TREATMENT



FAILURE REPAIR AREA


PAVEMENT FAILURE REPAIR SEE CD-02 FOR DETAILS



DETAIL NUMBER




STANDARD DETAIL NUMBER CALTRANS STANDARD PLANS



PROPOSED PAVEMENT -MATCH LINE SEE BOTTOM LEFT WORK 中央 中央市 中央市 中央市 中央市 中央市 中央市 中央市 中央市 **LOCATION MAP** 

SECTION 8: OLIMA ST (COLOMA ST TO EBBTIDE AVE) TREATMENT: CRACK SEAL



SECTION 8: OLIMA ST (COLOMA ST TO EBBTIDE AVE) TREATMENT: CRACK SEAL

Know what's below. Call before you dig.

REVISIONS

1	i i	{			
				<b>7</b>	K
			7	· W	
				A	al
		©	2013 KIMLE	Y-HORI	N A
		6130 STON	ERIDGE MAL	L RD, S	STE
	l	PHO	ONE: 925-3	98-48	40

DATE BY

Kimley-Horn and Associates, Inc.

AND ASSOCIATES, INC. 370 PLEASANTON, CA 94588 25-398-4840 FAX: 925-398-4849 WWW.KIMLEY-HORN.COM



	designed by	DRAWN BY	CHECKED BY				
PROFESSION E. PUNT	TH/JP	TH/CG	JP				
15/012	PLANS PREPARED UNDER SUPERVISION OF:						
6. 68897	JOHN PULLIAM, P.E.						
Com Sil	REGISTERED CIVIL ENGINEER						
OF CALIFOR	APRIL 2013		68897				
	DATE		RCE NO.				



## PROJECT LAYOUT PLANS OLIMA ST

PL-05 SHEET 08 of 27

CITY OF SAUSALITO 2013 STREET IMPROVEMENT PROJECT

JOB No. 097901001

DRAWNG NO