
Photographs from air, ferry plaza, access pier, Sausalito Yacht Club parking lot and facilities of story poles showing new access pier and gangway and "story buoys" showing the float





Staff photograph of Ferry Landing via Fire Dept ladder truck with story poles showing new gangway



Staff photograph of Ferry Landing via Fire Dept ladder truck with story buoys" showing the float






Staff photographs of Ferry Landing from SYC parking lot with story poles showing new access pier and gangway and "story buoys" showing the float










Staff photographs of Ferry Landing from plaza area with story poles showing new access pier and gangway and "story buoys" showing the float







Staff photographs of view from southwestern corner of Sausalito Yacht Club (SYC) deck with story poles showing new access pier and gangway




Staff photographs of view from southwestern Sausalito Yacht Club (SYC) deck with story poles showing new access pier and gangway





Staff photographs of view from middle of southeastern Sausalito Yacht Club (SYC) deck with story poles showing new access pier and gangway



Staff photographs of view from corner of southeastern Sausalito Yacht Club (SYC) deck with story poles showing new access pier and gangway









Staff photographs of view from northern Sausalito Yacht Club (SYC) deck











Staff photographs of view from tables in bar at Sausalito Yacht Club (SYC) with story poles showing new access pier and gangway










Staff photographs of view bar at Sausalito Yacht Club (SYC) with story poles showing new access pier and gangway









Staff photographs of Ferry Landing from end of existing access pier with story poles showing new access pier and gangway